

SM2246EN Flash F/W & ISP Release Information – P1228BS
Introduction

This purpose of this document is to provide release information on the SM2246EN F/W and ISP release information

Fix Coverage

- stands for the “new fix” or “new support” in the category
- stands for the “no-update” in the category

■ Tester FW	■ Controller ISP
<ul style="list-style-type: none"> □ Yield Issue ■ Flash Issue <ul style="list-style-type: none"> □ SLC Flash <ul style="list-style-type: none"> □ Samsung Flash □ Toshiba/Sandisk Flash □ Intel/Micron Flash □ Hynix Flash □ Others ■ MLC Flash <ul style="list-style-type: none"> ■ Samsung Flash ■ Toshiba/Sandisk Flash ■ Intel/Micron Flash ■ Hynix Flash □ Compatibility issue □ Tester Bug Fix ■ AP Bug Fix & New Function ■ Feature Enhance 	<ul style="list-style-type: none"> ■ Yield Issue ■ Flash Issue <ul style="list-style-type: none"> □ SLC Flash <ul style="list-style-type: none"> □ Samsung Flash □ Toshiba/Sandisk Flash □ Intel/Micron Flash □ Hynix Flash □ Others ■ MLC Flash <ul style="list-style-type: none"> ■ Samsung Flash ■ Toshiba/Sandisk Flash ■ Intel/Micron Flash ■ Hynix Flash □ Compatibility issue ■ ISP Bug Fix □ Feature Enhance

ISP Revision History

Version	MP Tool version	ISP version	Note
P1228BS	Q0203A	P1228BS	<p>This FW supports Intel/Micron L06B 3D MLC NAND (featuring SLC caching)</p> <ol style="list-style-type: none"> 1. Update Security FW to version: Q0126A. 2. Support L06B whole drive SLC mode(except for system blocks). 3. Support flush dram as SPOR feature for 3.3V devices. 4. Reduce command latency as GC is under operation. 5. Reduce time consumption on dram access in update/check map functions. 6. Return COMRESET status in ISR if COMRESET occurs in Trim. 7. Add pretest error code: 0x29 to sort power-on one pass L06B. 8. Add RDT features: Read retry could be enabled in RDT by MP tool. 9. Add max/min Temp. in SMART ID: 0xC2(optional setting in MP tool). 10. Issue fix: Modify the cases that FW would clear command as LSCS occurs. 11. Issue fix: As enable/disable write cache is set by SCT command, the feature can not be changed by set feature command. Device should not return error as well. 12. Issue fix: Under force enable write cache, device should not return error as host disable it.
P0819AS	P0810A	P0819AS	<p>This FW is the first release of SLC caching FW.</p> <ol style="list-style-type: none"> 1. Only supports Intel/Micron L06B. 2. Please check the corresponded RDK for PCB modification, especially the extra capacitors which will be used for LPP (Lower Page Protection) 3. For the configuration of 4ch/4CE or 4ch/8CE, normal FW (non-SLC caching) is suggested instead of SLC caching FW.

Note:

1. F/W and ISP update is recommended.
2. History # is denoted by "Version-Date" .

This document is for information only and is subject to change without notice. Silicon Motion, Inc. reserves the right to make changes in the product design without reservation and without notice to its users.